

300 S. RANDOLPHVILLE RD. PISCATAWAY, NEW JERSEY 08854 TEL: 1-800-4-HOFFMAN FAX: 1-732-968-8371

Ship To: PICK UP

Invoice To:

BRANCH LOCATIONS

1144 ZEREGA AVE. 1330 HURFVILLE ROAD 120 GORDON DRIVE LIONVILLE, PA 19341 BRONX, NY 10462 DEPTFORD, NJ 08096

22 PECONIC AVE MEDFORD, NY 11763

1440 ROUTE 9W MARLBORO, NY 12542

Branch						
Marlboro NY				1		
Date	Time				Page	
01/05/24	08:	57:28 (0)		01	
Account No.	Phone No		1	Invoi	ce No.	
ARTHU004	8458561142			X04586		
Ship Via		Purchase Order				
Tax Exempt No.						_
141501491		TAX EXEMPT				
			Sale	sperso	on	
				388		

ARTHUR TROVEI & SONS, INC. 82 SLEEPY HOLLOW ROAD SPARROW BUSH NY 12780 Attention: . UNKNOWN SERVICE INVOICE

WARRANTY DATE HRS PIN/EIN HRS STK#/FLEET# 3973 3210017686 GRADALL C006195 XT.4100

QUESTIONS ABOUT YOUR SERVICE REPAIR INVOICE? PLEASE REACH OUT TO US. MARLBORO OPERATIONS MANAGER: DANIEL.SHAFER@HOFFMANEQUIP.COM

11/14/23 11/21/23 11/30/23 SEGMENT# 1 C 2459 N/A WILL NOT DRIVE FROM HOUSE CORRECTION: 12/4/23 #2448 installed new switch for parking brake in upper cab, checked fuse panel for blown fuses found all fuses are corroded and relays are corroded, machine will not release parking brake from upper cab, parking brake relay is not functioning, wires going to relay are corroded and main sericite board is corroded, new relay was ordered, the sericite board is corroded in many spots, informed service of findings 1/2/24 #2459 3973 HOURS CLEANED AND REMOVED CORROSION FROM FUES/RELAY PANEL IN UPPER STRUCTURE AND BEHIND FRONT COVER. TESTED CIRCUITS AND WIRING FOR THE DIG BRAKE. USED POWER PROBE TO SEND POWER THROUG THE CIRCUIT AND FOUND THAT EVERYTHING WOUD WORK PAST TRAVEL RELAY 1 AND 2. REPLACED TRAVEL RELAY 1 AND TESTED MACHINE AND IT WORKED AS IT SHOULD. REINSTALLED ALL REMOVED COVERS AND LOOSE SECTIONS OF THE HARNESS. ADDITIONAL DESCRIPTION: ALBERT IS CONTACT 845-856-1142 UNIT DROPPED TO SHOP 11/14/23 DRIVE NOT WORKING FROM SWING HOUSE SEAT , STEERING DOES WORK BRAKES WILL NOT RELEASE CONTINUED ON PAGE 02

TERMS: Net cash. Accounts in arrears more than thirty (30) days will bear interest at 1% per month. (12% ANNUAL RATE) Prices are subject to change without notice. Prices are F.O.B. at point of origin. Claims for shortages/errors must be made within five (5) days. Parts are returnable only with prior authorization. Returned parts must be accompanied by a packing list or invoice and are subject to a 20% handling/restocking charge and applicable freight. This invoice is subject to the terms and conditions of the sales transaction which is represented herein.





DOOSAN

CASE

ACCEPTED / CONFIRMED



300 S. RANDOLPHVILLE RD. PISCATAWAY, NEW JERSEY 08854 TEL: 1-800-4-HOFFMAN FAX: 1-732-968-8371		BRO 354	BRANCH LOCATIONS 1144 ZEREGA AVE. 1330 HURFVILLE ROAD 120 GORDON DRIVE BRONX, NY 10462 DEPTFORD, NJ 08096 LIONVILLE, PA 19341 22 PECONIC AVE 1440 ROUTE 9W MEDFORD, NY 11763 MARLBORO, NY 12542				
Ship To: PICK UP		Branch <u>Marl</u> Date	boro NY	Time		Page	
		01/0 Account N ARTH	No.	Phone No	57:28 (Q) 5. 58561142	02 Invoice No. X04586	
	_	Ship Via			Purchase Orde	r	
Invoice To: ARTHUR TROVEI & SONS, INC. 82 SLEEPY HOLLOW ROAD SPARROW BUSH NY 12780			Tax Exempt No. 141501491		TAX EXEMPT Salesperson 388		
Attention: . UNKNOW							
	SERV	ICE INVOICE					
STK#/FLEET# C006195 GRADALL XL4100	HRS PIN/EI 3973 321001	17686	ANTY DATE	3 F	HRS		
UNIT DOES HAVE TWO BATTERY S	HUT OFFS (DRIVER	MENTIONED)	00 E	~		45.00	
FRTIN	FREIGHT IN	2	22.50 159.47			159.47	
80263041	TIME DELAY REI		159.4			36.02	
80363132	CONTURA SWITCH		36.02			36.75	
86508603	RELAY	1	36.7: PARTS			277.24	
			LABOI			2623.75	
11000005		SEGMENT	TOTAL==:			2900.99	

*****	WORK	ORDER	TOTALS	* * * * * *
PARTS			2	277.24
LABOR			26	523.75
TOTAL DUE			29	900.99

PLEASE REMIT PAYMENT: HOFFMAN INTERNATIONAL INC. 300 S. RANDOLPHVILLE ROAD PISCATAWAY, NJ 08854

TERMS: Net cash. Accounts in arrears more than thirty (30) days will bear interest at 1% per month. (12% ANNUAL RATE) Prices are subject to change without notice. Prices are F.O.B. at point of origin. Claims for shortages/errors must be made within five (5) days. Parts are returnable only with prior authorization. Returned parts must be accompanied by a packing list or invoice and are subject to a 20% handling/restocking charge and applicable freight. This invoice is subject to the terms and conditions of the sales transaction which is represented herein.



DOOSAN

CASE

ACCEPTED / CONFIRMED

LeeBoy



- Ca

